



0000089862

ORIGINAL

## EAGLETAIL WATER CO., LLC

P.O. Box 157  
Tonopah, AZ 85354  
928-372-2236

RECEIVED

2008 OCT 23 A 10: 57

AZ CORP COMMISSION  
DOCKET CONTROL

October 18, 2008

Docket Control  
Arizona Corporation Commission  
1200 W. Washington St.  
Phoenix, AZ 85007

Arizona Corporation Commission  
DOCKETED

OCT 23 2008

Re: Docket No. W-03936A-04-0840  
Decision No. 67982



As per item #20 line 17 we are filing this quarterly report listing all revenue and disbursements from our Leak Fund. The above-mentioned Decision went into effect August 01, 2005.

Balance as of June 30, 2008 \$754.23

Revenue: Month of July	159.60	Disbursements	July 9 <sup>th</sup> \$140.00 labor
			July 27 <sup>th</sup> 155.00 labor
August	197.21		Aug 24 <sup>th</sup> 130.00 labor
September	125.87		0.00
Reimbursement for shed	632.28		
	-----		-----
	1869.19		425.00

Balance as of Oct. 18, 2008 \$1444.19

## Leak repairs as follows:

July 7<sup>th</sup> - Replace leaking valve between 539<sup>th</sup> and 540<sup>th</sup> Ave  
 July 7<sup>th</sup> - Repair broken line to meter (customer had hose hooked directly to meter, someone pulled on hose breaking meter hookup)  
 July 9<sup>th</sup> - Repair leak in 2" line south of airstrip. Also cap of 2<sup>nd</sup> line (preventive)  
 July 9<sup>th</sup> - Repair 4" main line east of Hook's  
 July 14<sup>th</sup> - Repair 4" main line on Pima Rd. at Lawrence's  
 July 26<sup>th</sup> - Replace leaking 6" blow-off valve at northeast corner of Harquahala Valley Unit 3. We think this was the major leak causing high water loss for a long time.  
 Aug 1<sup>st</sup> - Repair leak in 2" line along Baseline Rd. on Co. side of unused 2" meter  
 Sept. 2<sup>nd</sup> - Repair leak along 2" line along south fence at Hook's (cap off unused line)

In August we had a 24% water loss witch is significantly lower than our previous monthly losses. In September our loss was .5% witch is well below our target. We have found two additional leaks that will be fixed as soon as we can arrange to have them dug. We think we have finally found the major source of our water loss at the 6" blow-off valve. We will be monitoring water loss closely to make sure this is correct.

If there are any questions regarding this report please call 928-372-2236 or contact us at the above address.

Respectfully,  
Eagletail Water Co., LLC